

## IECEX Quality Assessment Report: CA/CSA/QAR15.0006/01 details

QAR :										
QAR Reference Number*: (automatic numbering)	CA/CSA/QAR15.0006/01									
Related QARs:	<a href="#">CA/CSA/QAR15.0006/00</a>									
Status*:	Issued									
QAR Free Reference Number*:	70107220									
Audit Date*: (yyyy-mm-dd)	2016-12-14									
Date of Issue*: (yyyy-mm-dd)	2017-02-15									
Details of change*:	Surveillance Audit									
Valid until*: (yyyy-mm-dd)	2018-10-06									
Site(s) audited*:	GfG Instrumentation Inc. 1194 Oak Valley Drive Suite 20 Ann Arbor Michigan 48108 USA									
Issuing ExCB*:	CSA - CSA Group									
Manufacturer*:	GfG Instrumentation Inc. 1194 Oak Valley Drive Suite 20 Ann Arbor Michigan 48108 USA									
Country of Manufacture*:	United States of America									
Product information*:	Multi-Gas Detectors									
Protection concept*:	Ex i Intrinsic Safety Ex d Flameproof Enclosures Ex e Increased Safety									
Related IECEX Certificates: (automatic linking)										
Related Certificates: (manual insertion)										
Related IECEX Certificates for previous versions:										
	<table border="0"> <thead> <tr> <th>ExCB</th> <th>CoC and Status</th> <th>Totals</th> </tr> </thead> <tbody> <tr> <td><input type="checkbox"/> CSA</td> <td></td> <td>1</td> </tr> <tr> <td></td> <td><a href="#">IECEX CSA 16.0052X issue: 0 [Current]</a></td> <td>1</td> </tr> </tbody> </table>	ExCB	CoC and Status	Totals	<input type="checkbox"/> CSA		1		<a href="#">IECEX CSA 16.0052X issue: 0 [Current]</a>	1
ExCB	CoC and Status	Totals								
<input type="checkbox"/> CSA		1								
	<a href="#">IECEX CSA 16.0052X issue: 0 [Current]</a>	1								
Comment:										
Attachment:										